Off-Channel Survey Report for: Last Modified: 8/13/98 At: 16:25:37 BK2RB2 Report Date: 8/13/98 By: bensoblb Page: 1

SITE INFORMATION

Site Identifier:

BK2RB2

Landowner Type: Private

Site Name:

03.0435X

Landowner Name: Puget Power

WRIA: Region:

NS

Address: Address2:

Trib to:

Lk Shannon

City:

River Mile: 7.10

State: Zipcode:

Phone:

River System: Legal Description: NE1/4S12T36NR8E

Baker R

Skagit

Habitat Type :

County:

lower valley wall tributary

Directions:

Site is most easily accessed by boat from the Lake Shannon launch. Site is on the left bank upstream approximately 5.5 miles. See map.

Area Overview :

Site is a small, low gradient stream that offers some fair spawning habitat and fair to good rearing habitat throughout the reach that is accessable. Large numbers trout were present. This stream has the longest anadromous reach of any site mapped draining into Lake Shannon.

Field Survey Information

Date: 7/20/98

Observer: Barkdull

Survey Type: initial

HABITAT INFORMATION

Water Source:

() Spring

() Groundwater

(x) Surface runoff

Flow:

() Intermittent(x) Year-round

Estimated Flows (cfs):

Lower end: 0.2

Upper end: 0.2

Water Temperature(C):

Lower end: None taken

Upper end:

Receiving Water Temperature (C):

Other Observations:

Site Area Measurements:

()Indirect

(x) Direct

() Combination

Widths: Channel:1.3

Ponds:

Wetlands:

Depths: Ohannel: 0.2

Ponds:

Wetlands:

Total length (includes ponds and wetlands):295

Total existing habitat area (est. m2):400

Spawning area: Impounded area: Mainstem:100 Mainstem:

Tribs: Tribs: Tribs: Total:100 Total:0 Total:400

Other rearing area: Unaccessible habitat: Mainstem:


Mainstem:400

Tribs:

Total:

Off-Channel Survey Report	for: BK2RB2	Report Date: 8/13/98	Last Modified : 8/13/98	At: 16:25:37	By: bensobib	Page: 2
Spawning habitat condit	ions: () No	ne () Poor (x) Fair	() Good () Exellent			
Describe spawning habi cobbles and silt. All is vo				graded grave	l and patches v	vith large
Rearing habitat condition	ns: () No	ne () Poor () Fair ((x) Good () Exellent			
Describe pond and othe of woody debris and is o with low banks, still low 273 meters the channel meters.	pen with tall ca gradient with m	anary grass surroundi nixed pools and riffles	ng the channel. At 65 n , good woody debris an	neters the stre d overhead co	eam enters an a over. A nice stre	alder forest eam. At
Describe unaccessible l	nabitat:					
Wetland type: () Bog	() Ma	arsh () Scrub-s	shrub () Fores	sted		
Describe:						
Flooding potential:	() Low	(x) Medium	High			
Describe: Strea	m appears to t	e moderately stable.				
FISH INFORMATION					•	
Site entry condition:	() Poor () Fa	ir (x) Good				
Describe: Strea	m is low gradie	ent and very accessat	ole where it enters Lake	Shannon		
Coho access and use:	Juvenile Adult	``	one () Poor () Fair (one () Poor () Fair (,		
Describe: Coho Baker Dam. Adult salm Baker Lake.			when spill occurrs or b lower Baker Dam and			
Other species access a	nd use: () Ch	num ()Pink ()Soc	keye () Chinook (x)	Trout		
Describe: Many	trout were obs	served on the day of t	he survey			
ENHANCEMENT OPPO	ORTUNITIES: 1	None				
Project type:						
Equipment acco	ess:				•	
ADDITIONAL COMMEN	ITS					
ATTACHMENTS AVAIL	ABLE				1	
() Aerials (x) Ske () Other References	tch (x) M	aps () Spawn	ing Surveys () Juver	nile Trapping		

Site id. code: BK2 RB2
Site name:
Scale: 1"-50 M
Observer(s): D. Barkdull
Legal location: NE 1/4512, T36 N, R8E Lk. SHannon Rm 7.1



7/20/98 trb to showing Lie 6.0 0.2 ofs faugry grass 26 18 who < /lo gradient

many fish (+17) observe

layer gravel & much sin

273 295 Dal 759 6.0 0.2 As Cayary grass much d